

1

## ABSTRACT OF THE DISCLOSURE

A method of masking areas of an object during galvanizing of the object to prevent galvanizing material from adhering to the masked areas comprising the step of applying a polyurethane adhesive to the area.

5

10

15

20

25